

| Kofferrfahrzeuge / box bodies | | | | | | | | |
|---|--------------------------------|----------------------------------|--------------------------|-----------------------|------------------------------|----------------------------------|----------------|-------------|
| | Typ/type | Artikelnummer/ reference code | Kondensator/condenser | Verdampfer/evaporator | Trockner/ drier | | | |
| Stirnwandkondensator / front-wall condenser | | | | | | | | |
| Frischdienst/ fresh cooling | FK 2350 | BNT-235001-001 | SKD119 12V | B76-045012-137 | VD2058/4/12V | B78-0200122020 | H14-003-065 | |
| | FK 2351 | BNT-235101-001 | SKD119 12-230V | B76-045012-144 | VD2058/4/12V | B78-0200122020 | H14-003-065 | |
| | FK 2650 | BNT-265002-001 | SKD119 12V | B76-045012-137 | VD3013/4/12V | B78-0250122503 | H14-003-065 | |
| | FK 2651 | BNT-265101-001 | SKD119 12-230V | B76-045012-144 | VD3013/4/12V | B78-0250122503 | H14-003-065 | |
| | FK 2750 | BNT-275001-001 | DKD324/12V | B76-091012-328 | VD3013/4/12V | B78-0250122503 | H14-003-081 | |
| | FK 2751 | BNT-275101-001 | DKD324/12V-230V | B76-091012-334 | VD3013/4/12V | B78-0250122503 | H14-003-081 | |
| | FK 2754 | BNT-275401-001 | DKD324/12V-400V | B76-091012-375 | VD3013/4/12V | B78-0250122503 | H14-003-081 | |
| | FK 2755 | BNT-275501-001 | DKD321/4/12V | B76-0520122581 | VD3013/4/12V | B78-0250122503 | H14-001-036-1 | |
| | FK 3050 | BNT-305001-001 | DKD324/12V | B76-091012-328 | VD4015/4/12V | B78-0530125304 | H14-003-081 | |
| | FK 3050 | BNT-305001-002 | DKD324/24V | B76-091024-329 | VD4015/4/24V | B78-0530245303 | H14-003-081 | |
| | FK 3050 | BNT-305002-001 | DKD324/12V-400V | B76-091012-375 | VD4015/4/12V | B78-0530125304 | H14-003-081 | |
| | FK 3050 | BNT-305009-010 | DKD324/24V-400V | B76-091024-344 | VD4015/4/24V | B78-0530245303 | H14-003-081 | |
| | FK 4250 | BNT-425001-001 | DKD514/12V | B76-095012-532 | VD4015/4/12V | B78-0530125304 | H14-001-058-1 | |
| | FK 4250 | BNT-425002-003 | DKD514/24V | B76-095024-536 | VD4015/4/24V | B78-0530245303 | H14-001-058-1 | |
| | FK 4250 | BNT-425001-002 | DKD514/12-400V | B76-095012-533 | VD4015/4/12V | B78-0530125304 | H14-001-058-1 | |
| | FK 4250 | BNT-425008-007 | DKD514/24-400V | B76-095024-537 | VD4015/4/24V | B78-0530245303 | H14-001-058-1 | |
| | Tiefkühlung / deep freezing | TK 2550 | BNT-255001-001 | SKD119 12V | B76-045012-137 | VD2058/6/12V | B78-0200122022 | H14-003-065 |
| | | TK 2550 | BNT-255101-001 | SKD119 12-230V | B76-045012-144 | VD2058/6/12V | B78-0200122022 | H14-003-065 |
| TK 2950 | | BNT-295001-001 | DKD324/12V | B76-091012-328 | VD3013/6/12V | B78-0250122508 | H14-003-081 | |
| TK 2954 | | BNT-295401-001 | DKD324/12V-400V | B76-091012-375 | VD3013/6/12V | B78-0250122508 | H14-003-081 | |
| TK 2955 | | BNT-295501-001 | DKD321/12V | B76-0520122579 | VD3013/6/12V | B78-0250122508 | H14-001-036-1 | |
| TK 4050 | | BNT-405001-001 | DKD324/12V | B76-091012-328 | VD4015/6/12V | B78-0430124302 | H14-003-081 | |
| TK 4050 | | BNT-405002-002 | DKD324/24V | B76-091024-329 | VD4015/6/24V | B78-0430244301 | H14-003-081 | |
| TK 4050 | | BNT-405007-008 | DKD324/12V-400V | B76-091012-375 | VD4015/6/12V | B78-0430124302 | H14-003-081 | |
| TK 4050 | | BNT-405009-010 | DKD324/24V-400V | B76-091024-344 | VD4015/6/24V | B78-0430244301 | H14-003-081 | |
| TK 5550 | | BNT-555001-001 | DKD514/12V | B76-095012-532 | VD4015/6/12V | B78-0530125302 | H14-001-058-1 | |
| TK 5550 | | BNT-555002-003 | DKD514/24V | B76-095024-536 | VD4015/6/24V | B78-0530245301 | H14-001-058-1 | |
| TK 5550 | | BNT-555007-005 | DKD514/12-400V | B76-095012-533 | VD4015/6/12V | B78-0530125302 | H14-001-058-1 | |
| TK 5550 | | BNT-555008-007 | DKD514/24-400V | B76-095024-537 | VD4015/6/24V | B78-0530245301 | H14-001-058-1 | |
| TK 8050 | | BNT-805008-006 | DKD514/24-400V | B76-095024-542 | VD4015/6/24V | 2x B78-0530245301 | H14-001-058-1 | |
| Unterflurkondensator/ underfloor condenser | | | | | | | | |
| FK | FK 2714 | BNT-271401-001 | UKD325/12V | B76-090012-330 | VD3013/4/12V | B78-0250122503 | H14-001-057 | |
| | FK 3414 | BNT-341401-001 | UKD331/12V | B76-090012-342 | VD4015/4/12V | B78-0530125304 | H14-001-057 | |
| TK | TK 2914 | BNT-291401-001 | UKD325/12V | B76-090012-330 | VD3013/6/12V | B78-0250122508 | H14-001-057 | |
| | TK 4014 | BNT-401401-001 | UKD331/12V | B76-090012-342 | VD4015/6/12V | B78-0430124302 | H14-001-057 | |
| Kompaktgeräte/ monoblock units | | | | | | | | |
| FK | FK 3950 | BNT-395006-005 | FK3950/12V/F | BFK-0300123903 | - | - | H14-003-081 | |
| | FK 3950 | BNT-395007-006 | FK3950/24V/F | BFK-0300243912 | - | - | H14-003-081 | |
| | FK 3954 | BNT-395014-013 | FK3950/4/12-400V, verst. | BFK-0300123909 | - | - | H14-003-081 | |
| | FK 3954 | BNT-395016-015 | FK3950/4/24-400V | BFK-0300243905 | - | - | H14-003-081 | |
| TK | TK 3950 | BNT-395001-002 | TK3950/12V/F | BTK-0375123903 | - | - | H14-003-081 | |
| | TK 3950 | BNT-395002-001 | TK3950/24V/F | BTK-0375243901 | - | - | H14-003-081 | |
| | TK 3954 | BNT-395010-009 | TK3950/12-400V | BTK-0375123907 | - | - | H14-003-081 | |
| | TK 3954 | BNT-395012-011 | TK3950/24-400V | BTK-0375243910 | - | - | H14-003-081 | |
| | TK 5950 | BNT-595003-003 | TK5950/24V/F HZ | BTK-0590245901 | - | - | H14-001-058-1 | |
| | TK 5950 | BNT-595004-004 | TK5950/24V/F HZ | BTK-0590245901 | - | - | H14-001-058-1 | |
| 2-Kammer Anlagen / dual-chamber units | | | | | | | | |
| Zwei-kammer / two-chamber | TF 5650 | BNT-755DUO-002 | DKD514/12-400V 2-K | B76-095012-543 | VD4015/6/12V VD3016/6/12V | B78-0430124302 B78-033012-328 | H14-001-058-1 | |
| | TF 5650 | BNT-755DUO-004 | DKD514/24-400V 2-K | B76-095024-541 | VD4015/6/24V VD3016/6/24V | B78-0430244301 B78-033024-327 | H14-001-058-1 | |